BEN MILAM

Elementary School

4200 McKinney Avenue Dallas, Texas 75205 Trustee District No. 2 Northwest Quadrant




Year Built: 1909 Building Area: 42,430 SF Site Acreage: 2.87 Optimal Student Capacity: 399
Enrollment (2018 - 19): 293
Campus Utilization: 73%
Facility Condition Index (Life-Cycle): 71.67%






Site Plans





Site Plans



LEGEND



Priority 1 & 2 Building Additions Priority 1 & 2 Interior Renovation


Priority 3 & 4 Building Additions Priority 3 & 4 Interior Renovation



Floor Plans

PROPOSED BASEMENT FLOOR PLAN





LEGEND

Selective Life Cycle Upgrades and Interior Finish Out

Priority 1 & 2 Building Additions

Priority 1 & 2 Interior Renovation


Priority 3 & 4 Building Additions

Priority 3 & 4 Interior Renovation



Floor Plans





LEGEND

Selective Life Cycle Upgrades and Interior Finish Out

Priority 1 & 2 Building Additions Priority 1 & 2 Interior Renovation


Priority 3 & 4 Building Additions Priority 3 & 4 Interior Renovation





Floor Plans





LEGEND

Selective Life Cycle Upgrades and Interior Finish Out

Priority 1 & 2 Building Additions

Priority 1 & 2 Interior Renovation

Priority 3 & 4 Building Additions

Priority 3 & 4 Interior Renovation



SUMMARY REPORT

Ben Milam Elementary School

Proposed Work Items

All costs are shown in 2018 dollars with soft costs included - NO INFLATION ADDED.

Priority		Total Cost
Priority - 1		\$1,839,500.00
Priority - 2		\$4,161,752.40
Priority - 3		\$6,889,740.00
	i ity T t Is	\$12,890,992.40

DISCIPLINE	PRIORITY 1	PRIORITY-2	PRIORITY-3	PRIORITY 4	COST
Civil	\$0.00	\$408,850.00	\$0.00	\$0.00	\$408,850.00
Building Envelope	\$32,500.00	\$442,838.50	\$572,520.00	\$0.00	\$1,047,858.50
Architecture	\$492,739.00	\$636,708.15	\$2,895,321.00	\$0.00	\$4,024,768.15
Mechanical	\$0.00	\$1,521,078.00	\$193,056.50	\$0.00	\$1,714,134.50
Electrical	\$0.00	\$303,374.50	\$0.00	\$0.00	\$303,374.50
Plumbing	\$0.00	\$113,750.00	\$947,154.00	\$0.00	\$1,060,904.00
Technology	\$162,500.00	\$0.00	\$0.00	\$0.00	\$162,500.00
Life Safety & Security	\$1,151,761.00	\$87,100.00	\$239,778.50	\$0.00	\$1,478,639.50
Athletics/Activities	\$0.00	\$111,803.25	\$0.00	\$0.00	\$111,803.25
Food Service	\$0.00	\$536,250.00	\$2,041,910.00	\$0.00	\$2,578,160.00
i ity T t Is	\$1,839,500.00	\$4,161,752.40	\$6,889,740.00	\$0.00	\$12,890,992.40
			T t ls 1		\$1,839,500.00
			Ttls 1 2	2	\$6,001,252.40
			Ttls 1 2	2 3	\$12,890,992.40
			Ttls 1 2	2 3 4	\$12,890,992.40

Ben Milam Elementary School Print Date: 10/10/2018 Page 1 of 1



Proposed Work Items

All costs are shown in 2018 dollars with soft costs included - NO INFLATION ADDED.

DETAILED REPORT

DISCIPLINE	ITEM NO.	ITEM DESCRIPTION	CLASS. CODE	PRIORITY CODE	SOURCE CODE	TOTAL COST					
CIVIL	CIVIL										
	C1	Remove and replace parking lot.	SPR	2	CA-DP						
	C2	Remove and replace concrete sidewalks.	SPR	2	CA-DP						
BUILDING ENVELO)PE					\$1,047,858.50					
	B1	Replace exterior waterproofing/sealant joints (include all exterior wall control/expansion joints, material transitions, around door and window frames, wall penetrations, etc.).	WS	1	CA-DP						
	B2	Replace outdated exterior windows with new energy efficient window assembly per DISTRICT STANDARDS.	WDW	2	CA-DP						
	В3	Paint all previously painted exterior surfaces and powerwash as required. Provide new landscaping and sidewalk replacement as required. Construct new front entry canopy .	REN	2	CA-DP						
	B4	Perform mild detergent medium pressure wash on stained or mildewed façade.	WRE	2	CA-DP						
	B5	Replace 2-ply modified bitumen roof system per DISTRICT STANDARDS.	RFR	3	CA-DP						
	B6	Replace spray foam roof system per DISTRICT STANDARDS.	RFR	3	CA-DP						
ARCHITECTURE	RE										
	A1	Renovate and expand administration area per DISTRICT STANDARDS (include vestibule, reception, admin offices, counselor suite, conference room, teacher workroom/lounge, clinic suite, restrooms, etc.).	REN	1	CA-DP						
	A2	Replace teaching surfaces (marker boards, tack boards, etc.) at each classroom.	MBTB	2	CA-DP						
	A3	Replace existing art room kilns and exhaust system and provide dedicated room (120 SF min.) per DISTRICT STANDARDS. (Includes, finishes, MEP upgrades, kilns, walls, etc.)	MEQ	2	CA-DP						
	A4	Paint all previously painted interior surfaces. Repair/patch walls prior to painting (except at areas of renovation).	PTG	2	CA-DP						
	A5	Remove and replace ceiling with new acoustical lay-in ceiling tile and grid throughout facility (except at areas of renovation).	CLG	2	CA-DP						
	A6	Replace carpet/vinyl composite tile (VCT) and base throughout facility excluding all main corridors, auditorium and athletic areas (include ACM abatement where applicable and except at areas of renovation).	FLR	2	CA-DP						
	A7	Renovate restrooms (include new wall and floor finishes, fixtures, toilet partitions etc.).	REN	3	CA-DP						
	A8	Replace stage curtains (include front, valance, etc.).	MEQ	3	CA-DP						
	A9	Replace interior doors and hardware. Re-key entire facility per new District "grand master" keying system.	DR	3	CA-DP						

Ben Milam Elementary School Print Date: 10/10/2018 Page 1 of 4



Proposed Work Items

All costs are shown in 2018 dollars with soft costs included - NO INFLATION ADDED.

DETAILED REPORT

DISCIPLINE	ITEM NO.	ITEM DESCRIPTION	CLASS. CODE	PRIORITY CODE	SOURCE CODE	TOTAL COST
	A10	Replace educational casework in all classrooms (excluding science labs) per DISTRICT STANDARDS (include counter tops, workstations and sinks).	CWK	3	CA-DP	
	A11	Renovate corridor to provide new durable surfaces throughout (remove existing lockers, floor, ceiling, and include ACM abatement where applicable).	REN	3	CA-DP	
	A12	Renovate and expand library into learning center based on DISTRICT STANDARDS.	REN	3	CA-DP	
	A13	Provide new flexible "next gen" furniture at Library per DISTRICT STANDARDS.	FRN	3	CA-DP	
	A14	Provide new flexible "next gen" furniture at Cafeteria per DISTRICT STANDARDS.	FRN	3	CA-DP	
	A15	Provide new flexible "next gen" furniture at all classrooms per DISTRICT STANDARDS.	FRN	3	CA-DP	
MECHANICAL						\$1,714,134.50
	M1	Provide VFD on chilled water pumps.	HVAC	2	CA-DP	
	M2	Replace split system AC units.	HVAC	2	CA-DP	
	М3	Replace rooftop DX units.	HVAC	2	CA-DP	
	M4	Replace lined ductwork.	HVAC	2	CA-DP	
	M5	Replace chilled water pumps.	HVAC	2	CA-DP	
	M6	Provide DDC controls.	HVAC	2	CA-DP	
	M7	Replace exhaust fans.	HVAC	2	CA-DP	
	M8	Provide test and balance of HVAC systems.	HVAC	3	CA-DP	
	M9	Provide commissioning of MEP systems.	HVAC	3	CA-DP	
ELECTRICAL						\$303,374.50
	E1	Replace interior lights with LED lighting.	LTG-I	2	CA-DP	
	E2	Provide interior lighting controls.	LTG-I	2	CA-DP	
PLUMBING	1					\$1,060, 04.00
	P1	Provide hose bibs.	PLF	2	CA-DP	
	P2	Replace grease waste piping.	PLGT	2	CA-DP	
	P3	Replace electric drinking fountains.	EDF	3	CA-DP	
	P4	Replace hot water piping.	PLDW	3	CA-DP	

Ben Milam Elementary School Print Date: 10/10/2018 Page 2 of 4



Proposed Work Items

All costs are shown in 2018 dollars with soft costs included - NO INFLATION ADDED.

DETAILED REPORT

DISCIPLINE	ITEM NO.	ITEM DESCRIPTION	CLASS. CODE	PRIORITY CODE	SOURCE CODE	TOTAL COST
	P5	Replace cold water piping.	PLDW	3	CA-DP	
	P6	Replace waste piping.	PLSS	3	CA-DP	
	P7	Provide 4 sinks at 6 classrooms (2 classrooms per grade levels 3-5). Includes additional casework and associated plumbing extensions/requirements.	PLF	3	CA-DP	
	P8	Provide one accessible sink at 4 classrooms (2nd grade level). Includes additional casework and associated plumbing extensions/requirements.	PLF	3	CA-DP	
TECHNOLOGY						\$162,500.00
	T1	Provide/replace IDF/MDF air conditioning.	HVAC	1	CA-DP	
LIFE SAFETY SE	CURITY					\$1,478,63 .50
	LSS1	Provide exterior lighting controls.	LTG-E	1	CA-DP	
	LSS2	Replace fire alarm system.	FA	1	CA-DP	
	LSS3	Replace exterior lights with LED lighting.	LTG-E	1	CA-DP	
	LSS4	Replace/Add security screens at first floor windows as per DISTRICT STANDARDS.	WDW	1	CA-DP	
	LSS5	Provide secure front vestibule. Include admin addition.	REN	1	CA-DP	
	LSS6	Provide new marquee sign located at front entry per DISTRICT STANDARDS.	SGN	2	CA-DP	
	LSS7	Provide new way-finding site signage.	SGN	3	CA-DP	
	LSS8	Replace exterior doors.	DR	3	CA-DP	
	LSS9	Replace intercom system.	PA	3	CA-DP	
	LSS10	Provide new room graphics and way-finding signage.	SGN	3	CA-DP	
ATHLETICS/ACTIV	ITIES					\$111,803.25
	AA1	Provide new/additional acoustical treatment at gyms.	ACO	2	CA-DP	
	AA2	Replace gym wall padding, backboards, goals and supports.	MEQ	2	CA-DP	
	AA3	Replace existing wood gym floor (include re-striping).	FLR	2	CA-DP	
FOOD SERVICE						\$2,578,160.00
	FS1	Renovate existing Cafeteria (include new finishes, acoustical treatment, lighting, sound system, etc.).	REN	2	CA-DP	
	FS2	Renovate kitchen and expand into existing Cafeteria (includes kitchen equipment, finishes and MEP upgrade).	REN	3	CA-DP	

Ben Milam Elementary School Print Date: 10/10/2018 Page 3 of 4



Proposed Work Items

All costs are shown in 2018 dollars with soft costs included - NO INFLATION ADDED.

DETAILED REPORT

DISCIPLINE	ITEM NO.	ITEM DESCRIPTION	CLASS. CODE	PRIORITY CODE	SOURCE CODE	TOTAL COS
	CODE	PRIORITY				TOTAL
	1	Must Do: Critical replacements of equipment & systems, safety & security (Life Expectancy: 0 - 2 years)	items and A	DA accessibi	lity	\$1,839,500.00
	2	Should Do: Replacements of equipment & systems, modernization of class exterior improvements (Life Expectancy: 3 - 5 years)	srooms & ha	illways and		\$4,161,752.40
3 Would Like to Do: Replacements of equipment & systems, programmatic campus renovations & additions to meet current standards (Life Expectancy: 6 - 10 years)				\$6,889,740.00		
						\$12,8 0, 2.40

FACILITY CONDITION INDEX (Life-Cycle Items Only)

The Facility Condition Index (FCI) is used throughout the facility assessment industry as a general indicator of building health. The FCI is calculated by dividing the Facility Condition Repair Cost by the Replacement Value. As a rule of thumb, an FCI of 0% - 10% is considered Excellent, 11% - 20% is Good, 21% - 40% is Fair, 41% - 59% is considered Poor, and 60% and above is considered Very Poor.

FACILITY CONDITIO	71.67%						
FACILITY REPLACEMENT VALUE	\$14,125,475.00						
FACILITY CONDITION REPAIR CO	\$10,124,072.40						
PRIORITY 4 TOTAL	0.00	0.00%	\$0.00				
PRIORITY 3 TOTAL	PRIORITY 3 TOTAL 5,343,559.00 100.00%						
PRIORITY 2 TOTAL	4,161,752.40	100.00%	\$4,161,752.40				
PRIORITY 1 TOTAL	618,761.00	100.00%	\$618,761.00				
PRIORITY MP TOTAL	\$0.00						
· · · · · · · · · · · · · · · · · · ·							

Ben Milam Elementary School Print Date: 10/10/2018 Page 4 of 4